Telephone (609) 588-0011 **LECO LABORATORY**

3123 Klockner Road Trenton, New Jersey 08690

Laboratory I.D. # NJ11106

CYO of Mercer County 794 East State Street Trenton, NJ 08600

Date Collected: 5-25-2021

Time Collected: 7:05am

Matrix: Water

Source: Child Care Area

Point of Collection: Girls' Lavatory Sink - Basement

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1452113

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	<0.002 mg/L
Copper (SM 3111B)		1.30 mg/L	0.326 mg/L
> = greater than	<= less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: June 7, 2021

By: ______ Donald B. Lilley/Director

Telephone (609) 588-0011

LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

CYO of Mercer County 794 East State Street Trenton, NJ 08600

Date Collected: 5-25-2021
Time Collected: 7:10am

Matrix: Water

Source: Child Care Area

Point of Collection: Water Fountain - Mezzanine

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1452114

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	<0.002 mg/L
Copper (SM 3111B)		1.30 mg/L	0.198 mg/L
>= greater than	< = less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: June 7, 2021

By: ______
Donald B. Lilley/Director

Telephone (609) 588-0011 LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

CYO of Mercer County 794 East State Street Trenton, NJ 08600

Date Collected: 5-25-2021

Time Collected: 7:13am

Matrix: Water

Source: Child Care Area

Point of Collection: Canteen Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1452115

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	0.0034 mg/L
Copper (SM 3111B)		1.30 mg/L	<0.10 mg/L
> = greater than	<= less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: June 7, 2021

Donald B. Lilley By: _

Donald B. Lilley/Director

Thisaces the replaced pure I replaced from June 23 1

Telephone (609) 588-0011

LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

CYO of Mercer County 794 East State Street Trenton, NJ 08600

Date Collected: 6-15-2021
Time Collected: 8:45am

Matrix: Water

Source: Child Care Area

Point of Collection: Water Fountain - Basement

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L166219

Parameter/Method	Limit	Result
Copper (SM 3111B)	1.30 mg/L	<0.10 mg/L
>= greater than <	= less than	
Remarks:		

rediffulks.

Copper meets the requirement established by the NJDEP.

Date: June 23, 2021

By: _____

Donald B. Lilley/Director

Telephone (609) 588-0011 **LECO LABORATORY**

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

CYO of Mercer County 794 East State Street Trenton, NJ 08600

Date Collected: 5-25-2021
Time Collected: 7:00am

Matrix: Water

Source: Child Care Area

Point of Collection: Water Fountain - Main Floor

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1452111

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	<0.002 mg/L
Copper (SM 3111B)		1.30 mg/L	0.345 mg/L
>= greater than	<= less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: June 7, 2021

By: _____ Donald B. Lilley/Director